

Corrosion Repair on Outer Tank Base with ARC S1



CASE HISTORY

1800 352 228

WWW.IMATECHENERGY.COM.AU

 **IMATECH**
ENERGY TECHNOLOGIES

SUMMARY

INDUSTRY : Refinery

PRODUCT : For Metal - ARC S1 For Concrete - ARC 791

EQUIPMENT : Storage Tanks

PROBLEM

Corrosion of the outer tank bottom, the edges and weld seam. Water collected in this area because the tank pad sloped towards the metal tank.

SOLUTION

Remove the bitumen cushion underneath the tank to a depth of 10 to 15 cm (4 to 6 in.) and a height of 4 to 6 cm (1.5 to 2.5 in.). After cleaning and preparing the exposed metal, apply two coats of ARC S1 covering this area including a strip of 30 cm (12 in.) above the bottom and around the tank.



SOLUTION

ARC 791 is used to reconstruct the bitumen base and to slope the surface towards the outside of the tank, preventing water from collecting under the tank. Final insertion of rubber gaskets and waterproof silicone sealant prevents any water infiltration.



RESULTS

The first 6 tanks were completed in November 2003. To date, the application is still in perfect condition, and the customer has completed the remaining tanks as well.



CONTACT US

Let us help you find out how our technicians can improve your operations and save you time and money.

Toll free : 1800 352 228
International : +61 2 8853 3000
Email : info@imatechenergy.com.au
Website : www.imatechenergy.com.au